BULDING SAFETY CERTIFICATE

No.3-181/2022

Dated: 28/02/2022

Certified that the MDN Future School, at Kesalwada Road, Tah-Lakhani, Dist-Bhandara 441804 comprised of ground floor basement(s) and owned/occupied by MDN Future School, at Kesalwada Road, Tah-Lakhani, Dist-Bhandara have complete with the building Bye laws in accordance with rule of State/UT, and incorporate the provisions of building safety as specified in National Building Code 2005, 2016 and as amended thereafter and has been verified by the concerned office on 03.03.2022 in the presence of Dr. Kundlik Mahadev Girhepunje, Lakhani and that the said above building/premises is safe an fit for running school with effect from 15.03.2022 for a period of 3(Three) years in accordance with rules.

Issued on 15.03. 2022 at Bhandara 441904 by PWD ZP Bhandara.

Signature with seal:

Authority:

Executive Engineer

Designation:

Zilla Parishad Bhandara

To,

MDN Future School

Kesalwada Road, Tah-Lakhani,

Dist-Bhandara 441804

ENDORSEMENT

The no objection certificate issued by department stand cancelled after completion of three years from date of issue.

Public Works Division

Perishad Shandara

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Na		N-FUTURE SCHOOL, KESALWA	A CO+
1	Name of the Officer	: - G. B. Patre, sectional Engin	
1.	Location Location	: = on Keralwada/wagh +all	
2.	Period for which the certificate is issued	: 3 years-	Road
3.		: = school Building (framed	2 meh
4.	Types of building	is lip Grown of floor & Front floor J. R. C.C.)	
5.	Nature of defect if any	: - No - Defect	
	a) Foundation and basement		
	b) Superstructure	: No Defect -	
	c) Doors and windows	: - No Defect -	
	d) Wood work wrought and put up		
	e) Roof	: - No Defect -	
	f) Flooring	: - No Defect -	
	g) Miscellaneous (Cracks if any)	:40 -	
6.	Any Major defects notices which will rende the building unsafe in any manner	r : _ No -	
7.	Whether maintenance works have been done properly	: - 725 -	- 51-
8.	Whether the structure is sound or not for conducting classes	: - sound -	
No	altitude intensity of wind exposure	ld be examined also with reference to loc or flood etc. ed necessary for the certificate may be furn	
	CERTI	FICATE	
	Certified that the School was inspe	ected by me on 3/3/2022	
	nd found to be fit / unfit to conduct clas	sees for the period 3 Years.	
		ses for the period	
fc	or the reason stated above.		
P	acc	(Seal)	
D	pate: 3/3/20.22		
	Reg Sub Div	risional Engineer Assistant Engineer	

कार्यालय, कार्यकारी अभियंता सार्वजनिक बांधकाम विभाग, जिल्हा परिषद, भंडारा

E-Mail

:- zpbhandara.ee@mahapwd.com eepwdzpbhandara@gmail.com

दुरध्वनी क्रं :- (०७१८४) २५२५७४

पत्र क्रं. भंजिप/साबांवि/आरे/९०७३/२०२२ दिनांक :१५/ / ८/२०२२

प्रति.

मुख्याध्यापिका

M.D.N.Future School, केसंलवाडा रोड, लाखनी

विषय : इमारतीचे फिटनेस/सुरक्षित असल्याचे प्रमाणपत्रबाबत

संदर्भ : १.मुख्याध्यापिका, MDN Future School, लाखनी यांचे पत्र क्रं.०६, दिनांक - ०२.०३.२०२२

२.उपविभागीय अभियंता, सा.बां.जि.प.उपविभाग, साकोली यांचे पत्र क्रं.८५६/२०२२,

दि.०३.०३.२०२२

संदर्भीय पत्राचे अवलोकन व्हावे. आपणाद्वारे आपले शाळेचे फिटनेस/सुरक्षित असल्याचे प्रमाणपत्र देण्यासंबंधाने मागणी करण्यात आलेली होती. त्यानुषंगाने उपिवभागीय अभियंता, सा.बां.जि.प.उपिवभाग, साकोली यांनी सदरहू शाळेस प्रत्यक्ष भेट देवून तांत्रिक बाबींची पाहणी व चौकशी करुन त्याबाबत तांत्रिक स्वयंस्पष्ट अहवाल या कार्यालयास सादर केलेला आहे. त्यानुषंगाने सदरहू शाळेच्या इमारतीचे फिटनेस/सुरक्षित असल्याचे प्रमाणपत्र यासोबत देण्यात येत आहे.

सहपत्र : फिटनेस/सुरक्षित असल्याचे प्रमाणपत्र

कार्यकारी अभियंता